

<b>ULTRA HELICOPTERS COMPONENT REPLACEMENT RECORD</b>							Due < 100	Due < 200	Due < 300
<b>Reg: C-GBPB</b>	<b>Date: 19-Jan-2011</b>				<b>A/F Starts 17265</b>	<b>Current TAFT:</b>	<b>20195.1</b>		
COMPONENT	S/N	TBO/ LIFE	TSO/ TSN	REMAIN.	INSTALLED AT		TO BE REPLACED		Hrs Remaining
					DATE	A/C HRS.	DATE	A/C HRS.	
Main Rotor Blades	A-4149	5000	4717.6	282.4	9-Sep-2003	15477.5		20477.5	282.4
206-010-200-133	A-4106	5000	4717.6	282.4	9-Sep-2003	15477.5		20477.5	282.4
Main Rotor Hub Ass'y	A1-00537	1200	987.9	212.1	4-Jan-2007	19207.2		20407.2	212.1
206-011-100-021									
Main Rotor Grips	HBFS-0060	4800	2729.1	2070.9	8-Nov-2003	17466.0		22266.0	2070.9
206-010-102-121A	HBFS-0052	4800	2729.1	2070.9	8-Nov-2003	17466.0		22266.0	2070.9
Main Rotor Trunnion	HB-1335	4800	2729.1	2070.9	8-Nov-2003	17466.0		22266.0	2070.9
206-011-113-103									
Main Rotor Straps	LPFS-31665	1200	87.1	1112.9	1-Jun-2010	20108.0	30-Jun-2012	21308.0	1112.9
206-011-154-105	LPFS-31663	1200	87.1	1112.9	1-Jun-2010	20108.0	30-Jun-2012	21308.0	1112.9
1200 HRS/2 YRS									
Main Rotor Pins	DIFS-17848	1200	987.9	212.1	4-Jan-2007	19207.2		20407.2	212.1
206-010-123-003	DIFS-18405	1200	987.9	212.1	4-Jan-2007	19207.2		20407.2	212.1
Main Rotor Fittings	MI-FS-530	1200	987.9	212.1	4-Jan-2007	19207.2		20407.2	212.1
206-011-140-001	MI-FS-391	1200	987.9	212.1	4-Jan-2007	19207.2		20407.2	212.1
Main Rotor Latch Bolts	DI-20234	2500	987.9	1512.1	4-Jan-2007	19207.2		21707.2	1512.1
206-010-260-103	DI-20051	2500	987.9	1512.1	4-Jan-2007	19207.2		21707.2	1512.1
Main Rotor Mast Ass'y	FAJF-56077	1500	419.6	1080.4	26-May-2008	19775.5		21275.5	1080.4
206-040-002-007		3000	1754.1	1245.9	26-May-2008	18441.0		21441.0	1245.9
Swashplate Assembly	JJG-09508	4800	812.9	3987.1	26-Jul-2007	19382.2		24182.2	3987.1
206-010-450-011									
Swashplate Support	A-002656	4800	897.3	3902.7	26-Jul-2007	19297.8		24097.8	3902.7
206-010-452-113									
Swashplate Sleeve	SI-405	4800	3300.6	1499.4	4-May-2001	16894.5		21694.5	1499.4
206-010-454-109									
Collective Link	REFS-4362	4800	1650.2	3149.8	22-Aug-2005	18544.9		23344.9	3149.8
206-010-407-001									
Collective Lever	REFS-3229	4800	1650.2	3149.8	22-Aug-2005	18544.9		23344.9	3149.8
206-010-467-105									
Input Driveshaft	A20-01163	12 mo	0.0	12 mo	1-Feb-2010	20095.1	28-Feb-2011		
206-040-015-103		600	100.0	500.0	1-Feb-2010	20095.1		20695.1	500.0
Transmission	BKW-184	1500	419.6	1080.4	26-May-2008	19775.5		21275.5	1080.4
206-040-002-025		4500	1754.1	2745.9	26-May-2008	18441.0		22941.0	2745.9
Freewheel Assembly	BMB10533	1500	1321.2	178.8	5-Sep-2007	18873.9		20373.9	178.8
206-040-270-003		3000	2500.1	499.9	5-Sep-2007	17695.0		20695.0	499.9
Clutch CL42250-1	FD-15242	3000	2500.1	499.9	5-Sep-2007	17695.0		20695.0	499.9
Tail Rotor Hub Ass'y	A-6584	2500	1125.5	1374.5	18-Jul-2006	19069.6		21569.6	1374.5
206-011-810-153									
Tail Rotor Blades	CS-2521	2500	812.9	1687.1	26-Jul-2007	19382.2		21882.2	1687.1
206-016-201-133	CS-2523	2500	812.9	1687.1	26-Jul-2007	19382.2		21882.2	1687.1
Tail Rotor Yoke	AFS-8752	5000	3615.2	1384.8	18-Jul-2006	16579.9		21579.9	1384.8
206-011-819-109		2500	1125.5	1374.5	18-Jul-2006	19069.6		21569.6	1374.5
Tail Rotor Gearbox	ALO-539	3000	2938.6	61.4	12-Apr-2002	17256.5		20256.5	61.4
206-040-400-005		6000	2938.6	3061.4	12-Apr-2002	17256.5		23256.5	3061.4
Tail Rotor Driveshaft	BTFS199	1200	100.0	1100.0	1-Feb-2010	20095.1		21295.1	1100.0
206-040-330-001									
Hydraulic Pump	BD-00752	3600	2528.1	1071.9	6-Jan-2006	17667.0		21267.0	1071.9
206-076-022-101									
Hydraulic Servo's	4162	3600	2355.7	1244.3	15-May-2003	17839.4		21439.4	1244.3
206-076-031-13	3566	3600	1566.6	2033.4	19-Jan-2006	18628.5		22228.5	2033.4
(4100670-005)	3806	3600	173.0	3427.0	13-May-2009	20022.1		23622.1	3427.0
Lower Collective Tube	USFS-3844	4800	812.9	3987.1	26-Jul-2007	19382.2		24182.2	3987.1
206-001-194-001									

ULTRA HELICOPTERS COMPONENT REPLACEMENT RECORD							Due < 100	Due < 200	Due < 300
<b>Reg: C-GBPB</b>	<b>Date:</b>	<b>19-Jan-2011</b>			<b>A/F Starts</b>	<b>17265</b>	<b>Current</b>	<b>TAFT:</b>	<b>20195.1</b>
<b>Engine Assembly</b>	820017	<b>O/C</b>	16352.6	O/C	5-Sep-2007	3842.5		<b>O/C</b>	
	Engine	Starts	17163			102	tracking only		
Gear Box	CAG-36731	<b>O/C</b>	10437.4	O/C	5-Sep-2007	9757.7		<b>O/C</b>	
6894171									
Compressor	CAC-32893F	1750	699.5	1050.5	5-Sep-2007	19495.6		<b>21245.6</b>	1050.5
6890550		3500	2327.2	1172.8	5-Sep-2007	17867.9		<b>21367.9</b>	1172.8
Impeller	KR-106561	3550	2327.2	1222.8	5-Sep-2007	17867.9		<b>21417.9</b>	1222.8
23058147	cyc	9150	3077	6073	5-Sep-2007	14188		<b>23338</b>	6073
Turbine									
6898734	CAT-38218P	3500	3338.0	162.0	5-Sep-2007	16857.1		<b>20357.1</b>	162.0
		1750	1507.3	242.7	5-Sep-2009	18687.8		<b>20437.8</b>	242.7
1 <sup>st</sup> Stage Wheel	546291	1775	1595.7	179.3	5-Sep-2007	18599.4		<b>20374.4</b>	179.3
23073853	cyc	3000	2180	820	5-Sep-2007	15085		<b>18085</b>	820
2 <sup>nd</sup> Stage Wheel	546054	1775	1595.7	179.3	5-Sep-2007	18599.4		<b>20374.4</b>	179.3
23073854	cyc	3000	2180	820	5-Sep-2007	15085		<b>18085</b>	820
3 <sup>rd</sup> Stage Wheel	HX-95676	4550	3338.0	1212.0	5-Sep-2007	16857.1		<b>21407.1</b>	1212.0
23001967	cyc	6000	4350	1650	5-Sep-2007	12915		<b>18915</b>	1650
4 <sup>th</sup> Stage Wheel	HX-76048	4550	3338.0	1212.0	5-Sep-2007	16857.1		<b>21407.1</b>	1212.0
6853279	cyc	6000	4350	1650	5-Sep-2007	12915		<b>18915</b>	1650
<i>Tie bolt - 23068265</i>	<i>NM-81449 cyc</i>	<i>9000</i>	<i>4350</i>	<i>4650</i>	<i>5-Sep-2007</i>	<i>12915</i>		<i>21915</i>	<i>4650</i>
Fuel Control Unit	BR-58607	1500	54.4	1445.6	27-Jul-2010	20140.7		<b>21640.7</b>	1445.6
2524644-31HX		2500	1529.1	970.9	26-May-2008	18666.0		<b>21166.0</b>	970.9
Governor	BR-44996	2000	1561.4	438.6	12-Aug-2008	18633.7		<b>20633.7</b>	438.6
2549170-2									
Fuel Pump	T103602	4000	2647.3	1352.7	5-Sep-2007	17547.8		<b>21547.8</b>	1352.7
6899253									
Fuel Nozzle	AG-45650	2500	2011.8	488.2	5-Sep-2007	18183.3		<b>20683.3</b>	488.2
23077067	deleted from 72-00-00 page 612 jun/2010	1500							
Bleed Valve	FF-22888	1500	1453.2	46.8	5-Sep-2007	18741.9		<b>20241.9</b>	46.8
23053176									
Starter Generator	11028	1000	866.6	133.4	30-Oct-2008	19328.5		<b>20328.5</b>	133.4
23032-018									

ULTRA HELICOPTERS COMPONENT REPLACEMENT RECORD							Due < 100	Due < 200	Due < 300
Reg: C-GBPB	Date:	19-Jan-2011			A/F Starts	17265	Current TAFT:	20195.1	
25 Hr Insp		25	0.0	25.0	25-Nov-2010	20195.1		20220.1	25.0
100 Hr Insp.		100	0.0	100.0	25-Nov-2010	20195.1		20295.1	100.0
200 Hr Insp		200	100.0	100.0	1-Feb-2010	20095.1		20295.1	100.0
300 Hr Insp		300	100.0	200.0	1-Feb-2010	20095.1		20395.1	200.0
600 Hr Engine Insp.		600	100.0	500.0	1-Feb-2010	20095.1		20695.1	500.0
1200 Hr Inspection		1200	100.0	1100.0	1-Feb-2010	20095.1		21295.1	1100.0
Annual Insp Mast		1 yr		1 yr	25-Nov-2010	20195.1	25-Nov-2011		
12 Mth Annual Insp		12 mth		12 mth	25-Nov-2010	20195.1	25-Nov-2011		
24 Mth Insp		24 mth		24 mth	1-Feb-2010	20095.1	28-Feb-2012		
Altimeter/Pitot Static 5934P-3	5K528	24 mo		24 mo	1-Feb-2010	19508.9	28-Feb-2012		
Battery Concorde	40248432	12 mth		12 mth	25-Nov-2010	20195.1	25-Nov-2011		
ELT 406AF-COMPACT	A78DF012350029D	12 mo		12 mo	25-Nov-2010	20195.1	25-Nov-2011		
ELT 406AF-Battery		24 mo		24 mo	30-Apr-2009	20019.6	30-Apr-2015		
Compass Swing		12mo		12mo	25-Nov-2010	20195.1	30-Nov-2011		
Survival Kit	BPB	12 mo	insp	12 mo	25-Nov-2010	20195.1	30-Nov-2011		
				Food		Rations	Expire	31-May-2012	
First Aid Kit	BPB	12mo	insp	12 mo	25-Nov-2010	20195.1	30-Nov-2011		
						Swabs	Expire	30-Nov-2011	
Fire Extinguisher P/N 46-0047-2	YH-24468	12mo	insp	12 mo	25-Nov-2010	20195.1	30-Nov-2011		
Cargo Hook 4232-4	878	3yrs	0.0	3yr	1-May-2009	20019.6	30-May-2012		
Fuel Cell Vent Tube <i>206-95-156/206L-95-180</i>	<i>CF-96-11</i>	300	0.0	300.0	25-Nov-2010	20195.1	25-Nov-2011	20395.1	200.0
		or Annual							
Boxbeam Inspection <i>CF91-35</i>	<i>CF-91-35</i>	12 mo		12 mo	25-Nov-2010	20195.1	25-Nov-2011		
		or Annual							
Exhaust type Cabin Heating <i>CF90-03R2</i>	<i>CF90-03R2</i>	100	0.0	100.0	25-Nov-2010	20195.1	30-Nov-2011	20295.1	100.0
		or Annual							
Tailboom Splice Insp <i>AD74-08-12</i>	<i>AD74-08-12</i>	100	0.0	100.0	25-Nov-2010	20195.1	30-Nov-2011	20295.1	100.0
Crosstube Assy Insp <i>AA-ASB94-04-5/94-04-6</i>	<i>CF-95-17Pt 1B</i>	300	0.0	300.0	25-Nov-2010	20195.1	25-Nov-2011	20395.1	200.0
		or Annual							
Flight Control Bolts <i>ASB 206-89-48</i>	<i>ASB206-89-48</i>	24 mo		24 mo	1-Feb-2010	20095.1	28-Feb-2012		
Fuel Boost Pumps <i>ASB206-05-103R"A"PT-IV</i>	<i>ASB206-05-103RA</i>	24 mth	clean	24 mth	9-Sep-2010	20159.3	30-Sep-2012		30-Sep-2012
	PT IV								
A/C Ground Receptacle <i>ASB206-10-126</i>	Verified - measured 0.4 no further action required.				3-May-2010	20108.0	N.F.A.R.		
Tail Rotor Blades <i>AD CF-2007-21R1</i>	ASB206-07-116R"B"	<b>N/A by S/N's Installed</b>			1-Dec-2010		N.F.A.R.		

N.F.A.R - No Further Action Required.